

25th, 12, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. "SAINT AIDAN"* Report *Gls.* No. *40230.*

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.09.)

Nature of Survey

When due


⊗ 100 A.1. (steel)

1 Dk. (steel) "Well Dk"


FPT 31 t. APT 12 t.

BK. 7" 3BH. Cerm Lloyd's AYCP Q81', BB' F24'

Machy Afr.



005480-005488-0149



9-8-20