


Lloyd's Register of Shipping.

SURVEYORS.

NEW ZEALAND CHAMBERS.

483 COLLINS STREET.

ADDRESS. "REPORTS."
OFFICE NO. 3386
PRIV. RES. X 1309



Melbourne, 9th Dec., 1936.

The Secretary,
LONDON.

M.

Dear Sir,

S.S. "AKUNA"

The freeboards as set out in your assignment letter dated 10th July last have now been marked on the ship's sides and the conditions of assignment complied with as follows:-

(1) All overboard scupper pipes from the second deck have been fitted with non-detachable screw plugs at the inner ends.

(2) All sanitary discharge pipes from spaces on the second deck have been fitted with second automatic non-return valves accessible at all times.

The freeboard certificate and copies have been issued as instructed and Freeboard Verification Report is enclosed herewith.

I am, Dear Sir,

Yours faithfully,

B. P. Fielden



© 2021

Lloyd's Register
Foundation

005635-005643-0052

Referred to the Chief Ship Surveyor.
(Freeboard).

H/B

11 JAN 1937

*Particulars noted on report
Cert. issued*

*Bob
11/1/37*



© 2021

Lloyd's Register
Foundation