

50,812.

F.E.

Received by Chief Ship Surveyor

26/4/13

Received from Chief Ship Surveyor

VESSEL'S NAME

St Elizabeth Bromby Rpt. Hul

No. 26128

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

27.62

Depth "d"

8.08

Framing: Table No

2 pages

Description

Ordinary

Longitudinal No.

2734

Proportions

Length = 11.0
Depth

Deck Sheerstrake

as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100A-1. (Std) as recommended.

+ 100A-1. (Std)

100 (2d)

NB = DTF 12 146

FK 5BH Cmn. Lloyds A + 60 Ncky Aff



© 2020

Lloyd's Register
Foundation

005756-005778-0263

Angles on upper edge

Tie Plates

Deck Material and thickness