


Tarica

It is submitted the Surveyor  
be requested to verify the  
size of the main generator  
cable. Should this not  
be 19/072?

19/072

J. H.  
11/12/41.



© 2020

Lloyd's Register  
Foundation

006258-006271-0144