

Sternframe No. 379 ship,
Rudder No. 379 ship.

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19 _____

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port *Newport*)

No. _____ SHIP FORGINGS ~~OR CASTINGS.~~

I have to report that the undermentioned Iron ~~or Steel Forgings or Castings~~, manufactured by *The Darlington Forge Ltd.* of *Darlington* for the Vessel No. *379*, being built by *Monmouth S.B. Ltd.* of *Cheltenham* have been inspected by me as set forth below and found to be, so far as can be seen, *Sound.*

~~Forgings or Castings.~~

Lloyd's

No. *3894D*

MR

M. Robertson

Built Darlington 18.11.21

STERN FRAME.

RUDDER FRAME,

STEM.

Scrap Iron

Scrap Iron

Forged

4 1/4 x 5 x 6 1/4 x 5"

4 1/4 dia to 5 1/2"

on Inspection

Forged / Smithed

Forged / Finished

on Inspected

29.7.21-25.10.21

29.7.21-14.11.21

CASTINGS.

on Standard Test

Pieces.

Test—

per square inch

22-75

on per cent. ...

ending Test—

before fracture

Test—

given as


from ground ...

ing Test—

as according to Rules

found satisfactory ...

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



Water Cap

Tons.

68

68

33

(if any chargeable) £

To be paid at

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

23, 29.



© 2021

Lloyd's Register Foundation

006467-006478-0225

006467-006478-0226