

Surveyor 12/4/11

Received from Chief Ship Surveyor _____

Stl. S.S. "No 6"

Rpt. Tri.

No. 2641.

Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No. 27.74.

Depth "d" 7.96'

Plate No. ✓

Description Single angle.

1 No. 2701.

Proportions Length = 11.1
Depth =

Deck Sheerstrake and other scantlings as approved

"A" class.

vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to

✱ A - ("Steel") "For river purposes only" as recommended.

A - ("Steel") "For river purposes only"

IDK.

FK. 4BH. Cem.



Lloyd's Register Foundation