

1,500,118.

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "CANADIAN MINER" Rpt. Halifax No. 1270.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 58.5 Depth "d" under 17'

Framing: Table No. 3 Description Bulb angle as approved.

Longitudinal No. 15795

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{\quad}{\quad} = \frac{\quad}{\quad}$ 13:17

upper Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. (steel) as recommended.

1 Dk (steel).

Cell DB 213 466t. FPT 35t. APT 13t.

FK. 4BH. Cem. Lloyd's A9CP P28', B 65, F27'

M
WES.
22-6-20



© 2021
Lloyd's Register
Foundation

006760-006771-0046

BEAMS,