

F.E.

of Ship Surveyor

Received from Chief Ship Surveyor

NAME STEEL S.S. "WAR DRUMMER" Rpt. H. Kg No. 4802

Orders of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/6/92.

Reverse No. 71-02 Depth "d" 22-96
 Table No. 5 Description Angle frame and reverse bar with
Web frames as approved
 Longitudinal No. 23081
 Proportions Length = 9-6'
 Depth =
 Edge Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed 100 A.1. (steel) as recommended.

1 Dk. (steel). Webframes.

Cell DB 274' 644t. FPT 134t. APT 93t.


FK. 6 BH. Cem. Lloyds A.&C.P P 33', B 90', F 28'.

Date of Build 2-19.

M
AKS
7.8.19

The Surveyors should be requested to state whether additional strengthening has been fitted to the Poop Deck Beams, to their satisfaction if these beams have been fitted 5" x 3" x 3/8" angles as mentioned in report.

Mr. 17/8/19.



© 2021 Lloyd's Register Foundation

006787-006796-0307