

to Chief Surveyors _____

Received from Chief Surveyors _____

 VESSEL'S NAME Steel S.S. "Pennsylvania Sun" Report P.H. No. 4550.
For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Date of Survey _____ When due _____

✱ 100. A.I. "Shelter Dk with Freeboard."

"Carrying Petroleum in Bulk."

 1 Dk (Stl) + Shelter Dk (Stl) + web frames. Longitudinal Framing.
 Cell DB n E + B 84' f 40' 448t, FPT 186t, APT 84t.

FK, 18 BH (10 BH to Shelter Dk, 8 BH to upper Dk), pt. Cen. A + CP.

F44 in Shelter Dk. Trchy. aft.



© 2021

 Lloyd's Register
 Foundation