

Do. of exce
Do. above
Engine
Gross To

Im. 12.15.

Katameya

F.E.

Received by Chief Ship Surveyor 27.12.17

Received from Chief Ship Surveyor

VESSEL'S NAME *Sheelss War Daffodil*

Rpt. *Inv*

No. *705-2*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *83.*

Depth "d" *27.41*

Framing: Table No. *3. page 16*

Description *Bulk Angle as approved*

Longitudinal No. *33200*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.26}{}$

Deck Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100A.1. (Steel) as recommended.


15K (Steel)

Cell DB 34 1115L. F.P.T. 119L. a.P.T. 175L

FK. 6 BH. pl. Cam. Logs axep. P 49' B 113' F 39'

7

M
27.12.17
2)



© 2021

Lloyd's Register Foundation

007246-007256-0081

BEAMS, TH
"
"
BEAMS, Po