

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

VIC. 81.

Rpt.

Hul.

No.

52691

GLS

68373.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Type of Engine

COMPOUND.

If Boilers fitted with forced draught

No

Tail Shaft. If fitted with a continuous liner

No

If fitted with an outside gland of
approved type

yes.

This vessel's machinery ~~appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed~~ L.M.C. 11.44.

1 vertical boiler. H.P. 120 1/2

H.S. 500 ft G.A. 27 ft

Y Run

12.1.45



© 2021

Lloyd's Register
Foundation