

S.S. *Churton* *Liv* Rpt. No. *83108*

It is submitted the *Liverpool*.....Surveyors
be requested to state whether the screw shaft of this
vessel, ~~examined by them on~~, runs in oil
and is fitted with an approved oil gland at its after
end.

~~The Surveyors should be informed that in all future
cases when reporting surveys on vessels whose screw
shafts run in oil and are fitted with approved glands,
or other approved appliances, the type of gland should be
stated on the report.~~

SL
22/4/22.



© 2021

Lloyd's Register
Foundation

007528-007536-0224

Angle, Plate, Tee Bulb, or Channel
Spacing

Deck. Material thickness

In Liv 23. 11. 22.



© 2021

Lloyd's Register
Foundation