

n.n. "Kamakura Maru"

M. V. "Shichibu Maru".

It is submitted the Yokohama Surveyor be informed that the "Total underdeck tonnage" which is given in their F. & O. Rpt. as 17497.61 tons is obviously incorrect as this figure is also given as the "Gross" tonnage.

The figure required is the tonnage to the scantling deck i.e. the deck corresponding to the moulded depth of 42'-6".

It would appear that the tonnage of 8898.85 is measured to the deck below the scantling deck. They should therefore report the tonnage between this deck and the scantling deck in order that the correct records may be made in the Register Book.

W. S.

10.5.30.



© 2020

Lloyd's Register

Foundation