

2m. 1.19.

1

Musician

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME STEEL S.S. "SAINT BEDE" Report Greenock No. 17493.

**For the CHIEF SHIP SURVEYOR** \_\_\_\_\_

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/3/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

\* 100 A.1. (steel).

2 Oks. (steel).

Cell DB 331' 985 t. FPT 132 t. APT 20 t.

FK. 7 BH. Cem. Lloyds A&CP. P 49', B 113', F 38'.

© 2020

Lloyd's Register  
Foundation