

1

Ulster, Castle

1 (2)

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. "SETTER"

Report

Gls.

No. 39941

For the CHIEF SHIP SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." Extract from Sub-Committee's Report, 24, 5, 892.

Nature of Survey

When due

\* 100 A. 1. (steel).

2 Dks. (U. S.R. ws.)

DTA 10' 27". DTf 4' 12". FPT 17".

BK 7". 4 BH. Cem. Lloyds A9 C.P. P 71', B 72', F 38'.



AES.

14-5-20

Lloyd's Register  
Foundation

007865-007873-0026

CENTRE GIRDER, in Dbl. bottom, dpth. &amp; thicknss.

Attached to outside plating with Angle.....