

Chief Surveyors _____

Received from Chief Surveyors _____

EL'S NAME "VAN GELDER" Report Liv No. 114797

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

of Survey _____ When due _____

In accordance with the practice in other similar cases, this Dutch vessel has now been generally examined afloat, as far as practicable.

The vessel had a full cargo of coal with the hatches battened down, and consequently the holds and hatch covers were not available for inspection.

This General Examination can, therefore, be regarded as of a partial character only, and to enable the customary ^{LR with date} notation of 'Examined' to be assigned it will require to be completed.

J.R.
17.9.40



© 2020

Lloyd's Register
Foundation