

28 FEB 1945

No. 22924

REPORT OF SURVEY FOR REPAIRS, &c.

Port of writing Report 6-1-1945 When handed in at Local Office 6-1-1945 Port of Greenock
 No. in Survey held at Port Glasgow Date, First Survey 20th Dec. Last Survey 28th Dec. 1944
 Reg. Book. on the Wood Iron or Steel M.V. "VAN GELDER" (No. of Visits 4)
 TONNAGE: GROSS 325 Owners Hollandse Zeereed By whom E. Benninghaus When 1914
 UNDER DK. 279 Managers J. Vermaas' Scheepvaart Bedrijf Owners' Address
 NET 230 Port belonging to Rotterdam
 Surveyed Afloat or in Dry Dock? Both Name of Dock Port Glasgow Destined Voyage
 Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Shell D B or D B a feet; uE & B feet; f feet
 Total capacity tons. FPT tons; APT tons; MT feet tons.
 Only alterations in the existing records of tanks should be inserted.
 N.B.—All alterations in the existing records should be underlined.

Last Report, No. Port

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as 40 cm ft
 painted on Ship and now verified

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR General Examination
 Now done: Vessel placed in drydock, bottom & rudder cleaned, examined & recoated.
 General examination made, as complete as practicable of the holds, machinery & accommodation spaces, decks, casings, ventilators, hatchways & closing appliances.
 Peak tanks examined internally & oil fuel bunkers externally. Windlars, general equipment & steering gear & its connections also examined & found satisfactory.
 Repairs: Shell rivets & caulking overhauled as found necessary. A few fractured beam keel rivets in fore hold (p.s.) renewed. 3 bulwark stays (p.s.f.) & one (p.s.a.) removed, faired & refitted & small doubling plate fitted on deck in way of the latter. Bulwark plate (s.s.f.) cropped & part renewed & bulwark stay & freeing port frame removed, faired & refitted. 20 hatch covers renewed. P.T.O.

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed ...								See report.
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	Good	Bulkheads	good	Engine Room Skylights	good	Copper, or Y.M.
Decks	"	Ceiling	"	Coal Bunkers, Openings, Covers, &c.	good	(State if on Felt)
Caulking of Decks	"	Cement or Asphalt	"	Oil Bunkers	externally	When fitted, Month Year
Coamings	"	Rudder	"	Scuppers	"	Boats
Beams & Fastenings	"	Steering gear and its connections	"	Cargo Hatchways	"	Masts, Yards, &c.
Outside Plating	"	Windlass	"	Hatches	"	Condition, how ascertained
" " in way of sidelights	"	Have pumps been examined and found efficient?	"	Planking	"	(State if wedges removed)
Frames	part end good	Have Sluice Valves been examined and found efficient?	"	Caulking	"	Equipment letter
Reverse Frames	"	Have Watertight Doors been examined and found efficient?	"	Treenails	"	Anchors, No. of
Longitudinals	"	Have Ventilators and their Coamings been examined and found efficient?	"	Breasthooks & Stemson	"	Cables (State if now ranged)
Transverses	"	Air and Sounding Pipes	yes good	Transoms, Pointers & Crutches	"	" length Stated mean diam.
Floors	part end good	Doubling Plates under Sounding Pipes	"	Timbers of Frame at openings	"	" Rule length sufficient size
Keelsons	"			" " at other places	"	Chain Locker
Stringers	"			Stringers, Clamps & Shelves	"	Hawsers & Warps
Inner Bottom Plating	"			Sanding	"	Standing and Running Rigging
Have the Tanks been examined internally?	Yes			(State if examined.)	"	Sails
Have the Tanks been tested?	No					

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

This vessel is eligible, in my opinion, to remain as classed with fresh record of docking survey 12.44 & notation of "Examined LR 12.44" for 12 months subject, as at present, to permanent repairs to indented keel & shell plating (p.t.s.), deck plating (s.s.), stem & stem plating (p.t.s.) & port house pipe at first opportunity.

Survey Fee (per Section 29) Gen. Exam. £ 3 : 0 : 0 Fees applied for, 38 FEB 1945
 Special Damage or Repair Fee (if any) (per Sec. 29) £ : : Received by me, 19
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :

Committee's Minute, Glasgow 27 FEB 1945
 Character Assigned, Secured for many repairs (12.44 P.G.I.)
 DUTCH V.S.

R.D. Welch
 Surveyor to Lloyd's Register of Shipping.

FRI. 19 JUL 1946

© 2020

Lloyd's Register Foundation

007458-007460-0332

4b.

in
Boo
40

lt
sin
alze
alce
oe.

12,45

SSER
e rema

1

1

1

10

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN

If Stockless, state Mechanical Test.

If Stockless, state Mechanical Test.

If Stockless, state Mechanical Test.

Lloyd's Register
Foundation

На