

1m,8,21.

F.E.

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "Cophthorne" Rpt. Abw No. 13296

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Depth "d" 15.0'

Description	Bulb angle
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50

Proportions $\frac{\text{Length}}{\text{Depth}} = 12.64$

Upper Deck Sheerstrake

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100 A1 (Steel)*

* 100. A. 1. (Steel)

1 Dk (Stl) "well dk."

Cell DB 192'38 t, FPT 40 t, APT 36 t.

FK, 4BH, Cem, Lloyd Ave. P16'967, B58, F23.



Lloyd's Register
Foundation

008020-008027-0176