

Lloyds
100/11

R. M. DE GRUYTER, A. I. N. A.

MARINE SURVEYOR—SURVEYOR TO LLOYDS AGENTS.
SPECIAL OFFICER SALVAGE ASSOCIATION, LONDON.

LOURENÇO MARQUES
P. O. BOX 452

SURVEY REPORT

I, the Undersigned Surveyor, to Lloyd's Agents, having been requested by Empresa do Limpopo, A. Couto Ltd., Owners of the T.S.S. "LIMPOPO" and Messrs. John T. Rennie & Sons, Lloyd's Agents, to survey the above vessel in drydock.

HEREBY CERTIFY that the vessel entered drydock on March 2nd, 1949, and bottom was cleaned of all marine growth.

Bottom stem, stern frame propellers rudder and pintles examined and found in efficient condition.

Doubling plate at curve of stem and doubling plate under stern, showing signs of getting thin were fitted with small doubling plates welded in place to cover the thin sections.

Bottom was then coated with anti-corrosive and anti-fouling paints and the vessel left the drydock on March 5th, 1949.

DATED AT LOURENÇO MARQUES THIS 24TH DAY OF MARCH, 1949.

© 2021

Lloyd's Register
Foundation

R. M. De Gruyter
SURVEYOR TO LLOYDS AGENTS