

1

Wm. Hamilton & Co.Ltd. Port Glasgow.Yard No. 445

Job No. 1029

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME LLANDUDNOReport GrkNo. 21796**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry.

~~When done~~

This is a twin screw minesweeper for the Admiralty and a sister vessel to the "ILFRACOMBE", "TENBY" etc.

On account of collision after launching damage to stern plating, framing etc. dealt with.

EA- "For Government Service" "Fitted for oil fuel 4.42 FP above 150° F"

2 Dks

Wing tanks aft 2lt, FPT 3t, APT 1ot

FK, 9BH

B &amp; F 110'

OL 173.9'

E.S.D.



© 2021

Lloyd's Register  
Foundation

008222-008230-0189

Floors, Depth and thickness at mid-line in  
Holds

12

12

✓

"

"

in way of

or