

COPY.

# Lloyd's Register of Shipping.



Port

GDYNIA

5 - NOV 1947

29/4/47

This is to Certify that I have

examined the ~~xx~~ <sup>Part</sup> ~~Boiler~~ and Machinery of the M.V. "Sobieski" of 1000 Tons Gross of Gdynia whilst lying afloat and in drydock at Gdynia and Gdynia on the 25/II/46 and subsequent dates.

that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have recommended that the record of + L.M.C. C.S., (with date)

be made in the Register Book in the case of this vessel when the survey has been completed.

(From Port)

now examined:—

Main Engine No. 1, 5, 7, 8 cylinders, pistons, covers, valves & connecting rods and top ends, Bottom ends and eccentrics. 6, 7, 8 Connecting rods and top ends, Bottom ends and eccentrics. 6, 7, 8, 9, 10 Journals.  
Starboard Main Engine. 6, 7, 8 cylinders, pistons, covers, valves & gears. 3, 5, 6, 7, 8 connecting rods and top ends, Bottom ends and eccentrics. 3, 6, 7, 8, 9, 10 Journals.  
Air Receivers. Port and Starboard internally.  
Liary Air Receivers. Port and After Port internally.  
Liary Generators. No. 1 Port: No. 2 Centre in their entirety.  
rical Circuits. Megger Tested.  
llers and outside fastenings.

*A. Clive. Jumper*

Engineer Surveyor to Lloyd's Register.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
Committees of the Society use their best endeavours to ensure that the functions of the Society are properly understood that neither the Society nor any Member of any of its Committees is under any circumstances responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Member thereof, or the Surveyors, or other Officers or Agents of the Society."