

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19__

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port Hartlepool)

F. 14078. SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~ castings, manufactured by Messrs. W. Shaw & Co
Middlesbrough for the Vessel No. 919, being built
Messrs W. Gray & Co of W. Hartlepool
has been inspected by me as set forth below and found to be, so far as can
seen, sound.

~~ings or Castings~~

LR.
7556
W.M.

Malcolm

Invariant

Middlesbrough

~~STERN FRAME.~~

~~RUDDER FRAME.~~

~~STEM.~~

S.M. Steel
Cast

Inspection ...

Rough Machine

Inspected

12.9.21; 14.9.21; 5.10.21.

TINGS.

Standard Test
aces.

are inch

30

er cent. ...

2290 in 2"

Test—
fracture

120°

ground ...

10H

Test—

rding to Rules
satisfactory ...

Yes

ETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

T.C.

Weight 2. 15. 3. 0

any chargeable) £

e paid at

state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

008507-008514-0181

BEAMS, Forecastle Deck, Angle, Bulb Angle,
Plate, Tee Bulb, or Channel

82 3 46 82 3 46

Deck. Material and thickness