

NAME OF VESSEL ..... "FORT. PITT" .....

Extract from freeboard verification of marking form received  
from the Vancouver ..... Surveyors dated the 23rd July, 1942.

|  |                    |                       |
|--|--------------------|-----------------------|
| Moulded depth                              | 37 ft.             | 4 ins.                |
| Corresponding draught                      | 26 ft.             | 11 $\frac{1}{2}$ ins. |
| Moulded depth as shown<br>on draught sheet | 37 ft.             | 4 ins.                |
| Tropical freeboard                         | 9 ft.              | 11 $\frac{3}{4}$ ins. |
| Summer                                     | " 10 ft.           | 6 $\frac{1}{2}$ ins.  |
| Winter                                     | " 11 ft.           | 1 $\frac{1}{4}$ ins.  |
| W. N. A.                                   | " not ft. assigned | ins.                  |
| Fresh water allowance                      |                    | 7 $\frac{1}{4}$ ins.  |

Marked from ~~wood~~/steel upper deck.

Note: Certificate endorsed for deeper loading.

Checked by H.M. .....

Date 9.10.42. .....



© 2021

Lloyd's Register  
Foundation

008641-008647-0005