

1

Saint Bernadette

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

S.S. "Louie Rose"

Report

Gls.

No. 43820.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry.

When due

+ 100A1 (Stal)

1 Dk (stl.)

"Well Dk"

Lell. D.B. f 169' 420t. F.P.T. 101t. A.P.T. 62t

F.K 4 B.H. Cem. Lloyds A.H.C.P. Q 156' Bon Q 13' F 23'

"machy alt"

[Handwritten signature]
[Handwritten signature]

[Handwritten signature]

[Handwritten signature]
 17.7.24

It is concluded the inner surfaces of the bottom are covered by cement but the Surveyor should state if this is so.



© 2021

Lloyd's Register

008641-008647-226 Foundation