A. 3m,6,32.

FREEBOARD REPORT on the S.S. "AUGSBURG"

It is submitted the Freeboards given on the accompanying form, as those required by the Tables, merit approval, the same to be marked on the vessel's sides, inserted in the certificate of classification, and recorded in the Register Book. subject to

1. The fidley openings being covered by strong steel covers permanently attached.

2. Efficient means of closing being provided for all ventilator coamings.

It is concluded that the sanitary discharge pipes 12'-6" below the upper deck do not lead from spaces below the freeboard deck, but the Surveyors should confirm this.

This vessel is classed 100A1 "Shelter deck with freeboard" in the Society's Register Book and in view of this it was ~~assumed~~ arranged that the vessel ~~might~~ would be surveyed and freeboards assigned in accordance with the International Convention by the Society on behalf of the Berufsgenossenschaft.

It is therefore submitted a copy of the freeboard report and a copy of the assignment letter be forwarded to the Hamburg Surveyors for issue to the See-Berufsgenossenschaft to enable them to assign freeboards and issue certificates to this vessel.

When the freeboards are marked the Surveyors should verify the markings and forward the usual verification of marking form to this Office in order that the freeboards may be recorded in the Register Book.

S.T.B.

25. 3. 33.

© 2021 Lloyd's Register Foundation

008648-008655-0254