

Port

Glasgow.

1,500,10.17.

1

Alice Marie

Sent to Chief Surveyors 10.1.18

Received from Chief Surveyors

VESSEL'S NAME

Steel S.S. Philotis

Report

Sb

No. 37386.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

❖ 100 A-1 (Steel) Shelter Deck with freeboard


1 DK (Steel) & Shelter Deck (Steel)

Gall D.B. u B 40' x 100 1965, F.P.T. 815 A.P.T. 135

F.K. 3 BH. can Lloyd's are.

M
10.1.18

The approved plan of Engine & Boilers. Sealing
chimes be forwarded for filing with the report, as
this does not appear to have come to hand.



© 2020
Lloyd's Register
Foundation
008743-008750-0243

Freeboards compared and found correct by

date

Form for Certificate