

" W. GASPARI
Rona Head

119.

F.E.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Stat S. S. "BLACK COCK"

Rpt. Sou No. 11065

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 37.5

Depth "d" 9.5


Framing: Table No. 3

Description Single Angle

Longitudinal No. 6206

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.7}{}$

Deck Sheerstrake as approved



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100-A-1. (Steel) as recommended

1 DK (Steel) ~ Well Dk

Cell DB 93' 146t, FPT 20t

FK, 3BH, Cam, Plythe A. P.

Q 95' B 11' F 23'

Wdry Off

[Signature]

[Signature]

3/-10-21



© 2021

Lloyd's Register Foundation

008855-008862-0061

BEAMS, Bridge Deck, Angle, Butt angle, Tee Butt, or Channel.....

Angles on upper edge

Spacing

43

43

Angle on ditto.....

54
54
3.3
53
3.3
53
3.3
15