

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

S NAME EMANUELA C REPORT Gro. 17401
Ans. 21731 No.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engine 4 S.C.S.A.
6 cylinders 330 - 600 mm
MN 130 (B.H.P. 650)

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner No
If fitted with an outside gland of approved type Yes

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter dated 18.3.57 for a speed of 325 RPM.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed
+LMC
ES 6/58


30.7.58

© 2020
30.7.58



Lloyd's Register
Foundation

008888-008849-0092