

Port of NEWCASTLE/ON/TYNE

12th July, 1945 10x

REPORT ON MASTS, SPARS, AND RIGGING.

W R Hook

Having, in accordance with your instructions,
examined the Masts, Spars, Iron Work of same, and Rigging, of the

(Name of Vessel) S.S. "RALOO"

on the (Date of examination) 21st May 19 45.

I have to report that I found Foremast and Topmast in good condition.

FORE RIGGING - Port side No. 1 and 2 shroud corroding badly,
recommend renewal.

Starboard side No. 1 shroud corroding badly, recommend renewal.

" " No. 2 " recommend cleaning and reserving.

MAIN MAST RIGGING - Port side No. 1 and 2 shrouds recommend
cleaning and reserving.

Starboard side No. 1 and 2 same as above.

MAIN TOPMAST - badly shaking, recommend renewal.

MAINMAST - in good condition.

All Screws and Shackles recommend annealing and oiling.

Fee £ 12: 6:

To the Surveyors,

Lloyd's Register of Shipping,

W R Hook



© 2021

Lloyd's Register
Foundation