

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME SK So "PENEF" Report GLS No. 50693

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey 1st Entry When due Revised Rule Rule

✠ 100 A. I. (Steel) With keelboard.

2 D^o (Stl)

Cell D.B. ~~237'~~ ⁴⁵ 237' 475' F.P.T. ~~74E~~ ⁷⁸ A.P.T. 124E

F.K., 6 B.H., cem, Clays ACP.

P 25', B 76', F 29'.



© 2021

Lloyd's Register Foundation

[Signature]
11.9.30

The Surveyor should be requested ~~to~~ ^{to} state whether the lengths:
• Capacities of the double bottom ^{are} tanks are correctly reported.

Is fee paid? _____

Form for Certificate

8009058-0090666-0066

1x3