

Lloyd's Register of Shipping.

(Report on Vessel No. 8703 Port Cpr)

No. 404 SHIP ~~FORGINGS OR~~ CASTINGS.

~~No~~ have to report that the undermentioned ~~Iron or Steel Forgings or~~ Castings, manufactured by Strømmen Versted of Strømmen for the Vessel No. 51, being built by Nahskov Skibsværft of Nahskov have been inspected by us as set forth below and found to be, so far as can be seen, sound and free from defects.

Mark on ~~Forgings or~~ Castings.

B
Lloyd's
5-11-31
S. No. 8142
P.E.


Guide

Fergim Kari

oslo, 5.11.31

	STERN FRAME.	RUDDER FRAME.	STEM.
Material*	...	<u>Steel</u>	
How made	...	<u>cast</u>	
If annealed	...	<u>yes</u>	
Dimensions	...	<u>as per plans</u>	
Progress on Inspection	...	<u>Rough cast & finishes</u>	
Date when Inspected	...	<u>19/10 & 5/11 - 1931</u>	
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—			
Tons per square inch	...	<u>36.4</u>	
Extension per cent.	...	<u>26.4</u>	
Cold Bending Test—			
Angle before fracture	...	<u>180°</u>	
Drop Test—			
Height from ground	...	<u>8 feet</u>	
Hammering Test—			
If made according to Rules and found satisfactory	...	<u>yes, good</u>	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) kr. : :To be paid at oslo

© 2020

Lloyd's Register
Foundation

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.