

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "MOUNT PARK" Rpt. Brs No. 10673

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. 67.83 Depth "d" 20'

Framing: Table No. 3 Description Bulb angle as approved

Longitudinal No. 21030

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 9.9

Bulb Deck Sheerstrake as approved

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100-A-1 (Steel) as recommended

1 Dk (Steel)

Cell DB 263' 612t, FPT 90t, APT 90t

FK, 584, Cen, Rlyds Av CP, P28', B86', F32'

M
11.3.21



© 2021

Lloyd's Register
Foundation

009514-009521-0038