

5m,11,28.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

25 MAR 1929

VESSEL'S NAME Stl. tw. s. s. "MONTCALM" Rpt. Bel. No. 10134.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Belfast Surveyors report this vessel placed in dry dock, the bottom cleaned and coated and minor repairs effected. *S&P Turbines*
New Engines have been installed, *S&P gears to 2 shafts* new seatings fitted to suit the New Engines, additional intercostals fitted, and minor alterations carried out.

It is submitted the vessel appears worthy to remain as classed with record of survey 3,29, as recommended.

100A1
Shelter Dk. with fbd.
3,29 Bel.
Fitted for oil fuel etc.,



© 2021

Lloyd's Register
Foundation
22. 3. 29.

009522-009526-0093