

F.E.

of Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel S.S. "GLORIA". Rpt. Bbo. No. 5321

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

Reverse No. 31.75

Depth "d"

Fig: Table No. 3 page 9

Description

Longitudinal No. 3810

Proportions $\frac{\text{Length}}{\text{Depth}} = 12,3$

Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed as 100 A.— (Steel) as recommended.

1 Dk. (Steel) Well Dk.

FPT 19t.

FK. 3 BH. Cem. Q46', B9', F21'. Machinery aft.

Date of Build. 11.18

M
20. 2. 19.

The Surveyors should state by cable the date of Launch.



© 2021

Lloyd's Register Foundation

009570 - 009579 - 0047

Certs
not advised

[Handwritten signature]

The enclosed contains a copy of the report of the Committee on the

of the

of the

of the

of the

of the

and the committee found that it is essential that the committee be
of the

of the

of the

of the

of the

The enclosed contains a copy of the report of the Committee on the

of the

of the

of the

of the



© 2021
Lloyd's Register
Foundation

LOANAGE