

24335

Rpt. 12.

## FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Port

Vessel's Name *Hawaii Maru*

Official No.

No. in Reg. Book *368*

Port of Registry (For Foreign Vessels)

*Osaka*

Iron or Steel

*Steel*

State whether Classed by Lloyd's Register

*Yes*

Name of Owners

Date of Verification

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	<i>13</i> ft.	<i>8</i> ins.
From centre of disc to top of statutory deck line at awning or part-awning deck . . . }	ft.	ins.
Fresh water line above centre of disc . . .		<i>7</i> ins.
Indian Summer line above centre of disc . . .		<i>6½</i> ins.
Winter line below centre of disc . . .		<i>6½</i> ins.
<del>Winter North Atlantic line below centre of disc</del>		<i>—</i> ins.
Distance between the top of statutory deck line on vessel's side and the intersec- tion of the continuation of upper side of wood or iron deck with the vessel's side	at <i>shelter</i> main, spar or upper dk.	<i>1¾</i> ins.
	at <del>awning or pt. awning dk.</del>	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

*See cable from Kobe Surveyor  
Freeboards correctly marked  
received 15.1.16*

Surveyor.

(To be filled up in London Office.)

Statement No. *24335* Date of Committee's Minute*20.6.15*Particulars for Record  
in Register Book.

Moulded Depth . . .	<i>40</i> ft.	<i>9</i> ins.
Freeboard . . .	<i>13</i> ft.	<i>8</i> ins.
Corresponding Draught	<i>27</i> ft.	<i>9</i> ins.

Freeboards compared and found correct by

*AKU*

date

Is fee paid?

Form for Certificate

*A*

Instructions

date

Certificate written *18-1-16*

Noted for posting

*20.1.16*