

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "CRISTINA D'AMICO" REPORT GEN No. 25391.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine 2 Steam Turbines D.R. geared to one screwshaft

H.S. 26027 sq.ft.

M.N. 3200

S.H.P. 16,000

If Boilers fitted with forced draught YES

Tail Shaft. If fitted with a continuous liner YES


If fitted with an outside gland of approved type NO

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter dated 11.3.58 for a propeller speed of 114 R.P.M.

Similar calculations for the 150 KW. diesel generator set were approved in the Secretary's letter dated 9.5.58 for a speed of 400 R.P.M.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

(+ LMC
7.60 { 2 WT.B. 668lbs. (Supt. 626lbs. - 842°F)
{ S.G. 135lbs.
{ O.F.
{ Oil Tanker



© 2020

Lloyd's Register Foundation

009796-009804-0032