

Vessel's Name "IRWIN"

3m.7.28.

1

Received from Chief Surveyors _____

Sent to Chief Surveyors _____

Report

Gls

No.

49593

VESSEL'S NAME *Steel Liner* "IRWIN"

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

2nd Entry

When due

*Revised Rules.**+ A1 (Steel) with Freeboard.**For Service between Rameswaram and Tale Manaar.**1 D* (Teak) and Promenade D* (Teak)**FK. 7 BH Asp Lloyd's A+CP**FPT 31t. APT 54t*

© 2021

Lloyd's Register
Foundation

010079-010088-0021

(To be filed up in London Office.)

Statement No.

Date of Committee's Minute