

Date of writing Report 1st Sept. 1943. When handed in at Local Office. 1st Sept. 1943. Port of Mahrrö.  
No. in Survey held at Mahrrö Date First Survey 20th Aug. Last Survey 21st Aug. 1943.  
27297 on the Wood, Iron or Steel M/T "KATHRINE STENERSEN" (No. of Visits 2)  
TONNAGE - Built at Mahrrö By whom Hockemus Mek. V. A. B. When 1941. MONTH 12  
Under Dk 9400 Owners Hockemus Frampskilde II Owners' Address (if not already recorded in Appendix to Register Book)  
6100. Manager J. Hockemus Port belonging to Oslo.  
Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Mahrrö Stad's Destined Voyage Laid up since Aug. 1942.  
WB=Cell DR or DB a feet: uE&B feet: f feet: f Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)  
Total capacity tons: FPT tons: APT tons: MT feet to s  
N.B. - All alterations to the existing records should be underlined.

Last Report, No. Port  
In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined  
Was a damage  
report made by anyone else? If so, by whom?  
REPAIRS OR EXAMINATION AS PER RULE, FOR Bottom survey, and Equipment.

Vessel placed in dry dock, bottom, stern frame and rudder cleaned, examined & coated. Anchors and Chain Cables placed onboard as per particulars inclosed, which have been inserted in Mahrrö first entry Report No. 2156 on this vessel.

In complete survey:-  
The steering gear and the windlass is to be tried.  
It cannot be stated when the survey will be completed.

SUMMARY OF DAMAGE REPAIRS:-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Pl.	Beams	Inner Bot- tom Plates	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE								
Decks	Good	State of Tanks now exd. inside	No		Air and Sounding Pipes		Copper, or Y. M. of Wood Vessels	
Caulking of Decks	"	State of Tanks now tested	No		Dblng. Plates under Sounding Pipes	Good.	(State if on Feet.)	
Coamings	"	Bulkheads	✓		Engine Room Skylights		When put on, Month	Year
Beams & Fastenings	"	Ceiling	✓		Coal Bunkers, Openings, Lids, &c		Boats	Good.
Outside Plating	Good	Cement or Asphalt (State which.)	Good.		Oil Bunkers	Good.	Masts, Yards, &c.	From dle.
Breasthooks	✓	Rudder	Good.		Scuppers		Condition, how ascertained	None.
Transoms	✓	Steering gear and its connections	Good.		Cargo Hatchways		(State if wedges removed)	
Frames	✓	Windlass	Good.		Hatches		Sails	✓
Reverse Frames	✓	Have pumps now been examined and found efficient	✓		Blanking of Wood Vessels		Equipment letter	1+
Longitudinals	✓	Have Sluice Valves now been examined and found efficient	✓		Sealing	ditto	Anchors, No. of	3-1
Transverse	✓	Have Watertight Doors now been examined and found efficient	✓		Trunnels	ditto	Chain Locker	✓
Floors	✓	Have Ventilators and their openings been examined and found efficient	✓		Breasthooks & Stemson	ditto	Cables (State if now changed)	Yes. See Rpt.
Keelsons	✓				Transoms Pointers & Grutches	ditto	length	mean diam
Stringers	✓				Timbers of Frame at openings	ditto	(on board)	✓
Inner Bottom Plating	✓				Ditto Ditto at other places	ditto	Rule length	size
					Stringers, Clamps & Shells	ditto	Hawser & Warps	✓
					Saltine	ditto	Sanding and Running Rigging	✓

General Observations, Opinion as to Class, Recommendation, &c.:-  
This vessel is eligible, in our opinion, to remain as classed in the Reg. Book with no record of survey Mmo. 8.43, when the first entry has been completed.  
Please see Mahrrö first entry Report No. 2156

Survey Fee (see Section 29) ...  
Damage or Repair Fee (if any) ...  
Travelling Expenses (if chargeable) ...  
Surveyor's Fee (if any) ...  
TUES. 12 OCT 1943  
TUES. 23 OCT 1945  
Deferred // See minute on memo. F.E. 2156.  
Noted: No action pending completion of first entry survey 1.10.43  
Lloyd's Register Foundation



M/ "KATHRINE STENERSEN", Malmö F.E. Report No. 2156.

457	36	2	17	✓	61	17	2	0	✓	90	Hall's Patent.	Skoda Works. Magna.	7.6.40			
458	36	3	7	✓	61	17	2	0	✓	90	"	"	7.6.40			
459	36	3	20	✓	61	17	2	0	✓	77.5	"	"	7.6.40			
	260	1	16	✓					✓	257.5	"	"	7.6.40			
460	26	2	22	✓	6	3	18	26	3	3	0	✓	2612	Admiralty.	Skoda Works. Magna	7.6.40

1963 304 2 1/4 197 1/2 178 1/2 844.1.7 1040 300 2 1/2 16 that Gutshoffen. Dord. 30.5.41 J.G. ✓  
 Test for Special Steel Ch. cables.  
 2nd link.  
 to all. links.

Drops Test.

Stream.	Heads.	54:0:20	P.K. 966	23.2.40	Thanks.	26:3:3	P.K. 967	22.12.39
		54:1:13	P.K. 968	24.5.40		26:3:3	P.K. 969	17.5.40
		54:1:18	P.K. 970	24.5.40		26:3:11	P.K. 971	17.5.40
		24:3:13	P.K. 972	9.2.40				

