

Sept. 7.

For the information of Surveyors and the Committee only.

Received at

Office,

19

Lloyd's Register of Shipping.

(Report on Machinery, No.

Port

Vancouver.

No. *762*

ENGINE FORGINGS OR CASTINGS.

I have to report that the ~~same~~ Steel Forgings ~~or Castings~~, as herein described, manufactured by *Burns Dry Dock Co* of *Vancouver* for the Engines No. being constructed by of *Burns Dry Dock Co* for the Ship No. *110*, being built by *Burns Dry Dock Co* of *Vancouver* have been inspected by me as set forth below, and found to be, so far as can be seen, *sound & free from defects.*

an Forgings or Castings.

As per

Vancouver.

Lloyd's

No. *262*

S. 26/95

CRANK SHAFT.

STRAIGHT SHAFTING.

THRUST SHAFT.

INTERMEDIATE SHAFTS.

PROPELLER SHAFT.

6A
25
12.5
195.
ions
ss on
pection
on Standard
est Pieces.
e Test—
per square inch
ation per cent
ending Test—
before fracture
when Inspected

6425.
forged
to drawing
forged & completed
64200
287.
180° inch
20/4/26 - 12.5.26.

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:—

Now fitted & Mr. Marvelli

ee (if any chargeable) £

To be paid at

of iron, state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.

State if annealed *760*

State if annealed

010219-010228-0155

010219-010228-0160

© 2021

Lloyd's Register
Foundation