

Ship's name *ss. AKAMAS*

*Liverpool (8) #160841*  
*16/1/63*  
Port *Falmouth (GA)* No. *14347*

Class is subject to *None*

Last survey date *26/1/63*

Docking, Repair

*12 MAR 1963*  
M.E. bedplate found cracked at Port-fwd. corner through  
No. 1 bearing transverse repaired by Metlock; the  
Surveyor recommends that the main engine bedplate  
(Metlock 1/63) be examined by 7/63 (6 mos. limit).

C.S. Advanced:

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**, subject to and recommended.

*WD. - 1/8"*

*627*  
*12/3/63. X*



© 2021

Lloyd's Register  
Foundation