

Received by Chief Ship Surveyor.....  
GB

Received from Chief Ship Surveyor.....

SHIP'S NAME Non.Prop.Barge "C.M.S. 1" REPORT Trincomalee No. 5066

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This barge was built at Hong Kong and the class \*100A1 "Ceylon Coasting Service" with record of "DS 11,61" recommended WHEN a report has been received of its satisfactory condition on arrival within the service area.

For further particulars see endorsement dated 29.12.61.

The TRINCOMALEE Surveyors report (2,62), the barge generally examined afloat and found in satisfactory condition.

IT IS THEREFORE SUBMITTED the barge is now eligible to be classed \*100A1 "Ceylon Coasting Service" with record of "DS 11,61".

\*100A1 "Ceylon Coasting Service"  
DS 11,61.

Descriptive Notation: "Barge"

PARTICULARS FOR R.B.  
As per Endorsement  
dated 29.12.61.

*GO*

6.3.62.



© 2021

Lloyd's Register  
Foundation

010263-010275-0116