

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME _____

"A P U R E"

~~Report~~ Cable of **No. 12.1.60.**

Signature of Surveyor _____

It is submitted the attached list of original shell & deck thicknesses

e forwarded to the NEW YORK Surveyor(s)or ~~their~~ information, as requested, and they also be advised as follows by
able.

PURE THICKNESSES IN HUNDREDTHS OF AN INCH MIDSHIP HALF LENGTH
 SHELL KEEL SIXTYEIGHT A TO E INCLUSIVE FORTYSEVEN
 G FORTYFIVE H FORTYFIVE SIXTY AT POOP FRONT FIFTYFOUR BRIDGE ENDS
 DOUBLING FORTYFIVE STOP DOUBLING FORTYSEVEN ON A B D STRAKES UPPER DECK
 STRINGER FORTYFOUR STOP FIFTYFOUR IN WAY OF BRIDGE STOP
 DECK FORTYTWO BRIDGE DECK STRINGER THIRTYEIGHT INBOARD FIRST THIRTY
 SECOND FIFTYSIX STOP FIFTYTWO AT NUMBER ONE TANK THIRD FORTY CENTRLINE
 FIFTYSIX STOP FIFTYTWO AT NUMBER ONE TANK STOP

Cable NYk per S'

Lloyd's Register
Foundation

010484-010494-0326