

TONNAGE: 4310
GROSS

By whom: ...
Owners: BILLY HILL SURVEYORS

S.S. 'MARKAB'

Having regard to the fact that it has been reported to the Surveyor that the vessel grounded on her last voyage, it will be incumbent on him to make the customary examination of the vessel, her machinery, steering gear, windlass, etc. in order that it may be ascertained that everything is in an efficient condition, whether any damage has been sustained or that there is any evidence of leakage. As a result of this inspection, he will be in a position to convey to the Owners his opinion as to the necessity for recommending further examination in dry dock.

Before any notation of "Fitted for oil fuel" can be assigned, the oil tanks will require to be tested and facilities afforded for the satisfactory external examination of the structure in way of these compartments when they are under pressure.

IT IS SUBMITTED the Bremerhaven Surveyor be informed accordingly.

Lu Bhu: - 6/9

[Handwritten signature]

6.9.49.



© 2021

Lloyd's Register Foundation

010445-010501-0321

what I can gather, the matter has not been taken up with the