

Rpt. 9

Date of writing report 24.1.58

Received London

24 FEB 1958

Port COLONBO

No. 4121a

Survey held at COLONBO

No. of visits 1

First date and

Last date 16.1.58

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 16537 S.S. "KENZUI MARU" Gross tons 4583 Date of build 5-1929

Owners INUI KISEN K.K. Managers - Port of Registry KOBE

Engines made 1929 By J. READHEAD & SONS LTD Type RECIP STEAM.

No. of Main Engines 1 No. of Screws 1

No. of Main Boilers 2 SB W.P. 180LB

No. of Aux./Donkey Boilers - W.P. -

Surveyed Afloat or in Dry Dock DRY DOCK

Nature of Survey DOCKING & CONDITION

Was Damage Report issued? - Int. Cert. YES

Last Report (For Head Office only)

Records of Survey & Special Notations as per Register Book

Hull	Machinery
+ 100 A1	+ LMC NK.
SS OSA (DR) 2.56	ENGINES 2.56
DOCKING 8.57	BOILERS M. 9.57
	CL 10.56
	STEAM PIPES 2.56

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Good Wear Down of Stern Bushes 7/32" Oil Glands - Sea Connections -

Fastenings Good Has Screwshaft Tubeshaft been drawn? NO Date of Examination - Has Shaft been changed? -

Has Shaft now fitted been previously used? - Has Shaft now examined/fitted a continuous liner? - Approved oil gland? -

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides Side Centre

4 Crankpins & Bearings Side Centre

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS

The machinery of this vessel as now seen is in good condition and eligible in my opinion to remain as at present closed without fresh record of survey.

Date of Committee THURSDAY - 5 MAR 1958 Decision As now

50m,656. T. (MADE AND PRINTED IN ENGLAND.)



If certificate is required state where to be sent.

Lloyd's Register Foundation

010615-010823-0144

- 32 Essential Independent Pumps (Identify by position)
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
- 35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)
- 38 Independent Air Compressors, Coolers & Safety Devices
- 39 Air Receivers & Safety devices—Main 40 Auxiliary
- 41 Oil Fuel Tanks (Not forming part of hull structure)
- 42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?
- 44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD	STARBOARD	AUXILIARY EQUIPMENT
a Generators	l Generators & Governors
b Exciters	m Motors
c Air Coolers	n Switchboards & Fittings
d Motors	o Circuit Breakers
e Air Coolers	p Cables
f Control Gear, Cables, etc.	q Insulation Resistance
g Insulation Resistance	r Steering Gear Generators and Motors
h Insulating Oil Test	s Navigation Light Indicators
i Overspeed Governors
j Magnetic Couplings
k Air Gap

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat.
Spt.

Boiler Securing Arrangements

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

LEAVE THIS SPACE BLANK

Polking

It is submitted that this vessel is eligible to remain as CLASSED.


[Handwritten signature]
22/1/58

Survey fees ... **Rs 91/-**

Damage fee ...

Expenses ...

Date when A/c rendered. **22-1-58.**



© 2021

Lloyd's Register Foundation