

I. Pimblott & Sons, Ltd., Northwich

Yard No. 688

t to Chief Surveyors
GB

Received from Chief Surveyors.....

VESSEL'S NAME m.v. "MARBURY" REPORT Liv No. 130069For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24 /5/92.)

ure of Survey First Entry ~~When the~~

100A- "Barge for River & Estuary Service"

"Butts of keel plating elec. welded"

FPT 27t APT 17t

BK 5" on FK, 3BH, pt Cem

Mchy Aft

O.L. 105.4'

Extreme breadth over belting : 23.8'

"b"



1.0.8
© 2021
14.2.50

Lloyd's Register
Foundation

010783-010790-0093