

COPY

# LLOYD'S REGISTER OF SHIPPING



Port CASABLANCA

Date 27th January 1963


**This is to Certify that I have**

surveyed the **M/V "CHOPIN" of GDYNIA** Gross tons **6.987**  
afloat at CASABLANCA in order to ascertain that the bottom  
of the hull was not leaking after the voyage from GDYNIA to  
CASABLANCA by heavy weather.

and that I am transmitting to the Committee of Lloyd's Register of  
Shipping, London, a report, stating that all repairs recommended by  
me have been completed to my satisfaction, also that I am  
recommending that ~~she be~~ **xxxxx** fore peak, tanks n° 1 and 2 port and  
starboard having been emptied, were sounded for 16 hours  
and it was ascertained that there was not any leak.

The vessel can proceed on her voyages.

I recommend that the fore part of the bottom be specially  
examined at the next dry-docking.



**Ch. BACHELLERIE**  
Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS Annual Survey  
BiS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 150m,7,62 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register  
Foundation

010797-010804-0020