

Extract from Havre Rpt.8 No.7767 dated 5.10.37 on the
steel barge "SERVICE SHEEL VI"

New freeboard marks traced in, painted and verified,
provisional Freeboard Certificate as per copy forwarded
herewith now issued.

All cowl ventilators removed and stowed in hold and pump
room, wood plugs and canvas covers fitted to ventilator
and stove pipe coamings.

Wood plugs fitted to all goose neck ventilator air pipes.

Wood plug fitted to heavy oil engine (pump) exhaust pipe
under stern.

Washboards jointed at entrance doors to pump room and
accommodation and door fastenings overhauled and secured.

All sea connections closed.

Square windows at front and sides of wheelhouse boarded over.

All equipment and moveable gear on deck and in hold, secured.

Chain pipes to chain locker suitably closed.

Accommodation side scuttles and dummy ports overhauled, new
glass circles and joints fitted where necessary. Freeing ports
examined. No doors fitted. Oil cargo hatches closed. Small
hatches to peaks jointed and bolted.



© 2021
7.10.37
Lloyd's Register
Foundation

010992-011000-0224