

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *SH T.S. VIOLET*Rpt. *H. Kg* No. *6340*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. _____ ✓

Depth "d" _____ ✓

Framing: Table No. _____ ✓

Description *angle frames as approved*

Longitudinal No. _____ ✓

Proportions $\frac{\text{Length}}{\text{Depth}} =$ _____

Deck Sheerstrake _____

*as approved**Revised Rules*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel) "Jerry" "In Service between Penang and Brai"
 1 D" (Leak).
 Cell D.B. E 14' 10".
 F.K., H.B.H., Cem, Plyds A CP.

*[Signature]**[Signature]*
27.11.28

© 2021

Lloyd's Register
Foundation

011171-011185-0012