

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

31. MAY

Ship's Name **MS "ARCHON SERAFIM"** LR 540092

Gross tons 5324

Port of Registry **PIRAEUS**

Port **MALTA**

Date of build 1/50

Is there a Rpt. 9? **Yes**

Rpt. No. 3345

No. of visits 1

First date and

Last date 30.4.65

Interim Cert. issued & copy herewith? **yes**  
**B. -183**

Damage rpt. issued & copy herewith? **No**

Last rpt. (H.Q. only) **604 1742**

Date of completing rpt. 24.5.65

Surveyed at, if different from Port above ---

Surveyed afloat and/or in D.D. **D.D.**

Last date of examination in D.D. 30.4.65

Has a Load Line Survey been held? **No.**

Summer freeboard as verified **Not verified.**

State which additional Rpt. 8 is attached: ~~(S.R.L.)~~; (PS); ~~(H.Q.)~~; ~~(H.Q.)~~; ~~(H.Q.)~~

Survey fees

Damage fee

Expenses 15 - Od

D.S. £12 - 10 - Od

S.A. fee

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

I have surveyed the above-named ship in accordance with the Rules for **Docking Survey.**

Wear & Tear Repairs **Nil.**

Conditions of class : No repairs effected at this time to indented stem and stem plating which were examined and found to remain efficient. It is submitted that this item be presently retained in the S.R.L. as previously recommended.

Appendix **Nil.**

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with ~~W.N.G. McCulloch~~ fresh record of dry docking **4/65**

**subject to all outstanding conditions of class being dealt with as previously recommended.**

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

**WEDNESDAY 23 JUN 1965**

Minute

**DS 4.65 subject (h)**

**W.N.G. McCulloch**  
Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN  
CLASSN. CITEE

ALSO FOR

SPL FOR

RECEIVED  
C.S.S.  
RECORDS  
SEL

POSTING

HEADER

CERT



## Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name **MS " ARCHON SERAFIM "** LR 540092

D.S.

( **---** ) Due **---**Port **M A L T A**Rpt. No. **3345**

<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>	
In dry dock from	29.4.65	* Air & sounding pipes	
" " " to	1.5.65	Doublers under " "	
Shell plating	Yes good	Steering arrangements (main)	
Sternframe	Yes good	" " (aux)	
Rudder	Yes good	Windlass	
Was rudder lifted?	No.	Masts & rigging	N.E.
Plating, etc. in way of shell openings	Yes good	Hand pumps & suction	
Side scuttles & deadlights		W.T. doors	
Overbd. scuppers & discharges		Bulwarks, freeing ports, etc.	
F.P. spaces		Summer freeboard as verified	
Chain locker			
A.P. spaces			
Engine space			
Boiler space			
Under E. & B.		<u>EQUIPMENT:</u>	
Coal bunker		Equipment letter	a + 2" S.Q.
Tunnel & well	N.E.	Fee ltr., if diff. from eqpt. ltr.	---
Cement, asphalt, etc., on btm. shell		Anchors: No. on board	3B 1S
Weather decks		Cables { State if ranged	Not ranged.
* Casings		Length on board	Stated complete
* Deckhouses		Mean dias. range from	--- to ---
* Superstructures		Rule length	270 f. Dia. 2" (S.Q.)
* Skylights		Mooring ropes	Sufficient.
* Companionways			
* Hatchways			
* Ventilators			
Other items:			

\* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"

12m,11,63 (MADE AND PRINTED IN ENGLAND)

W.N.G. McCulloch

W.N.G. McCulloch

Surveyor to Lloyd's Register of Shipping

Lloyd's Register  
Foundation

0219 2/2



HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	↑	F.P. tank	↓	↑
"	'Tween decks		A.P. tank		
			D.B. tanks & c/dams		
No. 2	Hold	↓		↓	↓
"	'Tween decks				
No. 3	Hold	↓	O.F. bunkers	↓	↓
"	'Tween decks				
			Settling tanks		
No. 4	Hold	↓		N.E.	N.T.
"	'Tween decks				
			Deep tanks		
No. 5	Hold	↓		↓	↓
"	'Tween decks		Side tanks		
No. 6	Hold	↓	Wing tanks	↓	↓
"	'Tween decks				
			Other tanks:		
	Cargo battens	↓		↓	↓
	Ceiling, etc.				



© 2021

Lloyd's Register  
Foundation