

Westmore

F.E.

Received by Chief Ship Surveyor 25/11/12

Received from Chief Ship Surveyor

VESSEL'S NAME *At 'H' Cove*

Rpt. *Sea*

No. *25504*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/92.)

Transverse No. *68.12*

Depth "d" *19.96*

Framing: Table No. *3 page 11*

Description *Bulk angle as*

Longitudinal No. *9/253*

approved

Proportions Length = *13.49*
Depth

Upper Deck Sheerstrake *as per Rule*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \oplus 100A-1. (*Stub*) as recommended,

\oplus 100A-1. (*Stub*)

1st (Stub)

*WB = Bulk D/B a 100' w 3' + 13 1/2' f 112 800t FPT 170t APT 145t
D tanks in ER. P 12' 80t S 14' 105t
FK. 5BH. Gen. Lloyd a + 60. P 23' 860' F 28'*

011316-011329-0053



© 2021 Lloyd's Register Foundation